

Independent Market Operator
System Management PSOP Working Group

M.n

M n	6
L c n	IMO Board Room Level 3, Governor Stirling Tower, 197 St Georges Terrace, Perth
 d	Friday 19 June 2009
 n	Commencing at 9.00am until 11.30am

M n A n nc

		Ac / n
---	---	---------------

Section 5.6 Loss of Communication facilities

IMO queried whether the emergency contact list is formalised in sub clauses 3 and 4. System Management stated that it is informal at the moment but needs to be made more formal. System Management suggested that this could be achieved through the local black start guidelines request..

Section 6. Communication Systems for Curtailable Loads

System Management noted that currently they contact Synergy to curtail load and then Synergy is responsible for ensuring that

		Ac, n
---	---	--------------

System Management PSOP Working Group

		Action
	<p>procedure.</p> <p>System Management noted that this PSOP was a work in progress and is open to any specific comments and suggestions for improvements from Members. System Management noted that if there are substantial variations, it will provide the Working Group with a tracked change version of the PSOP.</p>	
	<p>There was no other business.</p>	
	<p>X M</p> <p>System Management stated that they will inform members of the details of the next meeting.</p> <p>It was noted that the next Monitoring & Reporting PSOP will be discussed at the next meeting.</p>	<p>Monday</p>
<p>L</p>	<p>The Chair declared the meeting closed at 11.30am.</p>	