



NSP and ISO to agree the CPC measures.

As Rio Tinto has submitted previously, there may be certain material requirements of the HTRs that may not be capable of being met by a facility “at a connection point” (even with the implementation of CPC measures). Rio Tinto assumes that the Coordinator’s intention in such cases is the registered NSP and ISO cannot be satisfied that CPC measures are sufficient to ensure that the integrated facility as a whole complies with the HTRs and therefore, must not accept the CPC measures proposed by the connection applicant.

Rule 274J sets out the process to be followed by the controller of an integrated facility and ISO where “relevant modifications” are proposed to be made to the facility. Rio Tinto notes that under rule 274J(3), whether a modifica